



瑞佑科技股份有限公司  
RAIO Technology Inc.

300新竹市科學園區工業東四路19-1號7樓  
TEL:886-3-5637888 FAX:886-3-5637666

## Comparison of RA6963L2NA/B-N & N1

<b>Model No:</b>	RA6963L2NA/B		<b>Date:</b>	May,05,2011
<b>To:</b>	Distributors/Agents of RAiO			
<b>Chips:</b>	RA6963L2NA/B-N & RA6963L2NA/B-N1			
<b>Description:</b>	Revising the incompatible problem of RA6963L2NA/B-N & T6963CFG and reading in "N1" on the Date Code to identify.			
<b>Version</b>	<b>RA6963L2NA/B-N</b>	<b>RA6963L2NA/B-N1</b>	<b>Note</b>	
<b>Fixed Item</b>				
Register set	THOME_R default 0	THOME_R default 16 (FFFFH)	Compatible with T6963CFG	
Register set	GHOME_R default 0	GHOME_R default 16 (FFFFH)	Compatible with T6963CFG	
Register set	TAREA_R default 0	TAREA_R default 8 (FFH)	Compatible with T6963CFG	
Register set	GAREA_R default 0	GAREA_R default 8 (FFH)	Compatible with T6963CFG	
Register set	OFFSET_R default 0	OFFSET_R default 5 (1FH)	Compatible with T6963CFG	
Register decoder set	Register Fully decoder	Register partial decoder	Compatible with T6963CFG	
Scrolling speed	Speed slower than the T6963CFG	The same with T6963CFG		
<b>Remove functions from RAiOs'</b>	Remove 1. Screen Reverse 2. Blink Time 3. Cursor Auto Moving 4. CGROM Font Select	The same with T6963CFG		
Driver Waveform	HOD slower than the ED HSCP	Repair HOD 1 HSCP slower than the ED	Compatible with T6963CFG	
Power on Reset	Take time more than T6963CFG POR	The same with T6963CFG		

RAiO Technology Inc.  
Information : +886-3-5637888  
[sales@raio.com.tw](mailto:sales@raio.com.tw)  
<http://www.raio.com.tw>

